





End view of 84" Culverts



Typical alligator cracks in asphalt



Drainage ditch with erosion defects



Post and chain fence to be removed





Concrete to be removed from roadway



Banks Pointe Subdivision
Roadway Improvements

September 2015

- Legend**
- Streams
 - Ponds
 - Asphalt Areas to be Repaired
 - Tax Parcel



THE WOOTEN COMPANY